



- 1 WASTE WATER MANIFOLD DISCHARGE
- 2 LPG LKR. DRAIN
- 3 COCKPIT DRAIN
- 4 ENG. DISCHARGE
- 5 GEN. DISCHARGE
- 6 GALLEY SINK DISCHARGE
- 7 HOLDING TANK DISCHARGE
- 8 TOILET INTAKE
- 9 BASIN DRAIN
- 10 TOILET DISCHARGE
- 11 COCKPIT DRAIN
- 12 WASH/DRY MACHINE DISCHARGE
- 13 SEA-CHEST INTAKE
- 14 TOILET INTAKE
- 15 TOILET DISCHARGE
- 16 SHOWER SUMP DISCHARGE
- 17 BASIN DRAIN

Certified ISO 9001 by



CLIENT : TAYANA-D48-107
 TITLE : THRU HULL LOCATION
 DRG NO. : 48107
 SCALE : N/A
 DATE : 2007/12/06
 DRG BY : Cherry



TAYANA YACHT BUILDING CO., LTD.