





	CHECK VALVE
	BALL VALVE
	COLD WATER PIPE - 1/2"
	HOT WATER PIPE - 1/2"
	WATER PUMP SHURFLD 5901-0211
	WATER STRAINER



Certified ISO 9001 by



CLIENT : TAYANA-D48-107  
 TITLE : FRESH WATER SYSTEM  
 DRG NO. : 48107  
 SCALE : N/A  
 DATE : 2007/11/22  
 DRG BY : Cherry



TAYANA YACHT BUILDING CO., LTD.